

MATERIAL SAFETY DATA SHEET

BUILDING PRODUCTS: CLAY BRICKS, PAVERS, ROOF TILES, FLOOR TILES, WALL TILES AND ACCESSORIES

These substances are classified as Hazardous according to criteria of Worksafe Australia.

IDENTIFICATION

Product Name: Fire Clay Products

Other Names: Bricks, Pavers, Blocks, Roof Tiles, Floor Tiles, Wall Tiles and Accessories

Manufacturer's Code: Not Applicable

UN Number: None Allocated

Dangerous Goods Class and Subsidiary Risk: Not Dangerous Goods

Hazchem Code: None Allocated

Poisons Schedule: Not Scheduled

Use: Building products used in Civil and Commercial Building Construction, Landscaping Applications and for Paving

PHYSICAL DESCRIPTION / PROPERTIES

Appearance: Varies from pressed, wirecut and special shaped bricks, pavers, floor and wall tiles in a wide range of colours and finishes. Terracotta roof tiles are a pressed profile and their finish is either fully semi-glazed or unglazed.

Melting Point: Not Applicable

Vapour Pressure: Not Applicable

Specific Gravity: 2.00 to 2.4 Kg/m³

Flash Point: Not Flammable

Flammability Limits: Not Flammable

Solubility in Water: Insoluble

Other Properties: Not Applicable

Ingredients: Fired vitrified clay or shale

CHEMICAL NAME	CAS NUMBER	PROPORTION
Crystalline Silica (α Quartz)	14808-60-7	0.1 to 50%

Other ingredients determined not to be hazardous:	50% to 100%
---	-------------

HEALTH HAZARD INFORMATION

HEALTH EFFECTS: The physical form of the clay products supplied by The Brickworks Group of Companies pose little or no risk to human health. Risks to human health may arise when the products are reworked liberating dust (which includes a hazardous component, crystalline silica) in a form which is respirable.

ACUTE EFFECTS:

Swallowed: Nuisance dust, mild irritant.

Eyes: Nuisance dust, mild irritant.

Skin: Unlikely to cause significant effects, may cause mild irritation from manual handling due to the abrasive texture and edges of some products.

Inhaled: If product is in an inhalable or respirable form, acute exposure may result in irritation to respiratory tract. If exposure is very large, then acute silicosis may occur. Acute silicosis is characterised by progressively laboured breathing.

CHRONIC EFFECTS: Chronic inhalation of crystalline silica may result in serious adverse health effects, particularly if the crystalline silica is of respirable size (approximately $< 7 \mu\text{m}$ aerodynamic diameter). Chronic exposure to crystalline silica in humans is associated with impairment of lung function. Reduced lung function may occur as a result of an increase in fibrotic tissue (silicosis), atrophy of gas exchange surfaces (emphysema) or airway obstruction (bronchiolitis).

Crystalline silica has been shown to induce lung cancer in laboratory animals and there is limited evidence that it may cause lung cancer in humans. The International Agency for Research on Cancer (IARC) has classified crystalline silica as a probable human carcinogen (2A).

FIRST AID:

Eyes: If in eyes, wash with water for 15 minutes.
If irritation persists, see doctor.

Inhaled: If discomfort or irritation occurs, remove to fresh air.

PRECAUTIONS FOR USE

Exposure Limits: Worksafe Australia has endorsed an interim Exposure Standard, Time Weighted Average (TWA), of 0.1mg/m^3 for Crystalline Silica.
However, where a State or Local Authority prescribes a standard lower than 0.1mg/m^3 , the lower standard applies.

Engineering Controls: Generating dusts from this product should be avoided. Where possible dampen materials before re-working. If dust generation is unavoidable, local exhaust ventilation or good natural ventilation should be employed. It is recommended that this product is wet sawn and drilled. Accumulated dust should be dry vacuumed or wetted and swept up. Wear suitable protective equipment for the eyes, skin and respiratory system.

Personal Protection:

Inhalation:	As appropriate particulate (dust) respirator should be used where dust may be generated. Respiratory protection should comply with AS/NZS1716 (1994) Respiratory Devices.
Eyes:	Eye goggles should be worn as a general precaution if dust is likely to enter the eyes.
Hands:	Gloves should be worn as a general precaution when handling fired product.
Flammability:	Not flammable.

SAFE HANDLING INFORMATION

Storage and Transport: No special requirements.

Spills and Disposal: If material is spilled, wet and sweep up area, or dry vacuum. Waste material should be bagged / wrapped and disposed in a manner which avoids generating dust.

OTHER INFORMATION:

CONTACT POINT: Occupational Health and Safety Manager or Site Manager.

For further information contact your nearest Austral Bricks, Eureka Tiles or Bristile Roofing Office

**NEW SOUTH WALES
(Austral Bricks)**
Wallgrove Road,
Horsley Park. NSW 2175
Telephone: (02) 9830 7700
Facsimile: (02) 9831 2383

**NEW SOUTH WALES
(Eureka Tiles)**
62 Belmore Road,
Punchbowl. NSW 2196
Telephone: 1300 387 352
Facsimile: 1300 765 792

**NEW SOUTH WALES
(Austral Bricks)**
1 Kiama Street,
Bowral. NSW 2576
Telephone: (02) 4861 1333
Facsimile: (02) 4861 4156

**VICTORIA (Head Office)
(Austral Bricks & Austral Masonry)**
Craigieburn Road East,
Craigieburn. VIC 3064
Telephone: 13 2742 (13-BRIC)
Telephone: (03) 9303 4000
Facsimile: (03) 9303 2319

**VICTORIA
(Eureka Tiles)**
Cnr Charlesworth & Stawell Streets,
Ballarat. VIC 3350
Telephone: 1800 810 185
Facsimile: (03) 5333 2587

**VICTORIA
(Austral Bricks & Bristile Roofing)**
41-55 Elliott Road,
Dandenong. VIC 3175
Telephone: (03) 8710 8710
Facsimile: (03) 8710 8700

QUEENSLAND
(Austral Bricks)
103 Riverview Road,
Riverview. QLD 4303
Telephone: (07) 3816 2934
Facsimile: (07) 3816 0508

QUEENSLAND
(Austral Bricks)
105 Gardner Road,
Rochedale. VIC 4123
Telephone: (07) 3347 2111
Facsimile: (07) 3343 2899

WESTERN AUSTRALIA
(Austral Bricks)
Harper Street,
Caversham. WA 6055
Telephone: (08) 9261 9999
Facsimile: (08) 9261 9988

WESTERN AUSTRALIA
(Austral Bricks)
245 South Western Hwy,
Armadale. WA 6012
Telephone: (08) 9399 0333
Facsimile: (08) 9399 6509

WESTERN AUSTRALIA
(Austral Bricks)
Military Road
Bellevue. WA 6056
Telephone: (08) 9250 0515
Facsimile: (08) 9274 5092

WESTERN AUSTRALIA
(Austral Bricks)
Kiln Road,
Cardup. WA 6201
Telephone: (08) 9550 6565
Facsimile: (08) 9525 1850

WESTERN AUSTRALIA
(Austral Bricks)
10 Bonner Drive
Malaga. WA 6090
Telephone: (08) 9249 7267
Facsimile: (08) 9249 7231

WESTERN AUSTRALIA
(Austral Bricks)
Dardarup Road,
Waterloo. WA 6228
Telephone: (08) 9276 3000
Facsimile: (08) 9276 3245

TASMANIA
(Austral Bricks)
Cressy Road,
Longford. TAS 7301
Telephone: (03) 6391 1511
Facsimile: (03) 6391 2121

SOUTH AUSTRALIA
(Austral Bricks)
Greenwith Road,
Golden Grove. SA 5125
Telephone: (08) 8251 1166
Facsimile: (08) 8251 4324